



If you find the rocker cover being interfered with by the thermostat housing, you may solve the interference by either spacing the housing forward with an additional gasket or two, or grinding (carefully) on the rear of the housing where it touches. Sometimes it will require a bit of both procedures.

DO NOT GRIND ON THE ROCKER COVER